## Search

	FILE 'CAPLUS, WPIX' ENTERED AT 10:01:27 ON 19 AUG 2004
L1	
L2	390226 SEA ABB=ON PLU=ON ?GLASS?
	TOTAL FOR ALL FILES
L3	1100388 SEA ABB=ON PLU=ON ?GLASS?
L4	21475 SEA ABB=ON PLU=ON (?GLASS? (5A) (GROUND OR COMMINUT? OR
	POWDER?))
L5	14919 SEA ABB=ON PLU=ON (?GLASS? (5A) (GROUND OR COMMINUT? OR
	POWDER?))
	TOTAL FOR ALL FILES
L6	('t-most form form out Conninted': On
	POWDER?))
L7	2145 SEA ABB=ON PLU=ON L4 AND FILLER?
L8	2086 SEA ABB=ON PLU=ON L5 AND FILLER?
	TOTAL FOR ALL FILES
Ь9	4231 SEA ABB=ON PLU=ON L6 AND FILLER?
L10	454 SEA ABB=ON PLU=ON L7 AND (THERMOSET? OR ?EPOX?)
L11	550 SEA ABB=ON PLU=ON L8 AND (THERMOSET? OR ?EPOX?)
	TOTAL FOR ALL FILES
L12	
L13	
L14	(Thouse (Si) (Column: OK HEGH: //
	TOTAL FOR ALL FILES
L15	2 SEA ABB=ON PLU=ON L12 AND (?ROUND? (5A) (CORNER? OR EDGE?))
L16	(= = 01 = 1011 = 1(= 10 + 10 )
	D ALL RN  0 SEA ABB=ON PLU=ON L10 AND (?RESPIR? (5A) ?GLASS?)  0 SEA ABB=ON PLU=ON L11 AND (?RESPIR? (5A) ?GLASS?)
L17	0 SEA ABB=ON PLU=ON L10 AND (?RESPIR? (5A) ?GLASS?)
L18	The second secon
	TOTAL FOR ALL FILES
L19	0 SEA ABB=ON PLU=ON L12 AND (?RESPIR? (5A) ?GLASS?)
L20	1 SEA ABB=ON PLU=ON L4 AND (?RESPIR? (5A) ?GLASS?)
L21	1 SEA ABB=ON PLU=ON L5 AND (?RESPIR? (5A) ?GLASS?)
	TOTAL FOR ALL FILES
L22	2 SEA ABB=ON PLU=ON L6 AND (?RESPIR? (5A) ?GLASS?)
L23	
	D 1-2 ALL RN